

Perkins Beach Groin Rehabilitation Edgewater Park





Sean E. McDermott, P.E. Chief Planning and Design Officer














Due Diligence – Lake Level Analysis

Static Water Levels | Cleveland Gauge














Due Diligence – Lake Level and Wave Height Analysis

Offshore Hindcast Waves

Design Water Levels

Return Period (years)	Monthly Mean Lake Level (ft, CD)	Storm Surge (ft, CD)	Combined Water Level ¹ (ft,CD ²)
2	3.3	1.4	4.9
5	4.1	1.7	5.6
10	4.6	1.9	6.0
20	5.0	2.1	6.3
25	5.2	2.2	6.4
50	5.6	2.4	6.7
100	6.1	2.7	7.0
Max Recorded Condition	+5.1 (June, 1986)	+2.6 (February 24, 1990)	+6.1 (February 2, 1987)















Due Diligence – Lake Level and Wave Analysis

Offshore Hindcast Waves





Prevalent waves from W

Largest storms from the north










Due Diligence – Hydrographic Survey






























Site Visit | Perkins Beach



Beach tapers east to west Arcs between groins













Site Visit | Perkins Beach



Rubble west end

Empty piers















GIS Comparison | Perkins Beach

































Edgewater Beach

Site Visit | Edgewater Beach



Beach tapers east to west

Salients develop behind concrete modules