










In January 1959 flood waters destroyed the old ford at Scenic Park in the Rocky River Reservation (above). By the end of the year the bridge pictured below had been engineered, built, and was open to traffic. Bridge Photo by R. Marvin Wilson.





















TRANSVERSE SECTION





BRIDGE DECK WEARING SURFACE REPLACEMENT DETAIL